




Enter/Exit Programming Mode



Motor Sleep mode off



Laser sleep mode off



Enter/Exit Programming Mode

